

Mandatory Personal Protective Equipment (PPE)

The following protective equipment and access card must always be worn within the yellow safety zone. However, drivers are allowed to await taking on a flame-retardant suit until unloading but must always wear full-coverage clothing and other protective equipment when getting out of the vehicle.




Helmet with chin strap

CE approved, EN 397





Safety glasses, goggles, visor or face mask







Access card Handed out at arrival and should be worn visibly





Gloves Visitors always. External workers according to the specific task





Hi-Vis, flameretardant fullcoverage clothing Long sleeves, long trouser legs and long socks covering the ankles







Safety footwear CE approved, EN 345



